INSTALLATION INSTRUCTION 300 Series LED Quick Connect[™] Socket Set

QP-LED303, MP-LED303

OVERVIEW:

Socket Set LED303 is designed for use with WAC MP-60E and all WAC quick connect canopies. Model MP-LED303 uses the same socket set as Model QP-LED303 except for QP-LED303 with a quick connector.

Model MP-LED303 is use with WAC power unit MP-60E. Model QP-LED303 is use with WAC the quick connect adapters: Solorail[™] (LM), Duorail[™] (LM2), Canopies (QMP), Line Voltage Tracks (H, J, L), Flexrail1[™] (HM1)

QUICK CONNECT[™] ADAPTER (order separately)


Solorail (LM) Adapter: LM-OADP Duorail (LM) Adapter: LM2-QADP Flexrail1 (HM1) Adapter: HM1-EN50 Line Voltage Track (H, J, L) Adapter: EN-HQ50AR, EN-JQ50AR, EN-LQ50AR

INSTALLING SHADE:

Position Socket Set LED303 so that threads through the hole in the shade and screw on Ring from below by finger or Ring Tool. (See diagram).

For model MP-LED303:

Put the knitted cable from the Socket Set into the cable grip (according to the steps 1,2,3, shown in the picture below)




For model **QP-LED303**:

- 1. Insert the post of the quick connect into the quick connect adapter.
- 2. Thread the top half of the conical section until it is flush with the adapter.
- 3. Adjust fixture position, but use caution not to loosen the conical section.

WAC LIGHTING

Responsible Lighting®



WAC Lighting www.waclighting.com Phone (800) 526.2588 • Fax (800) 526.2585 Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050

Western Distribution Center 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585


WAC Lighting retains the right to modify the design of our products at any time as part of the company's continuous improvement program. JULY, 2014

INSTALLATION INSTRUCTION 300 Series LED Quick Connect[™] Socket Set

QP-LED303, MP-LED303

TO INSTALL / SHORTEN THE CABLE:

Feed the cable end through the Top Conical section and the metal finial. If cable needs to be shortened, make the cut now. To install the top conical section, follow the step-by-step instructions bellow. **NOTE: PENDANT CABLES ARE CO-AXIAL, IF THE LOWER SCREW IN STEP 4 IS MADE TOO TIGHT, THE INNER AN OUTER WIRE WILL SHORT. A SHORT CIRCUIT WILL RENDER THE ENTIRE SYSTEM IN-OPERATIVE AND POSSIBLY DAMAGE THE TRANSFORMER. CHECK ALL PENDANT SPLICES FOR CONTINUITY BEFORE INSTALLING.**



WAC Lighting www.waclighting.com Phone (800) 526.2588 • Fax (800) 526.2585 Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585

WAC LIGHTING

Responsible Lighting[®]

WAC LIGHTING Responsible Lighting®

MP-60E

SAFETY INSTRUCTION


- Do not conceal or extend exposed conductors through a building wall.
- Do not install this system in wet locations.
- To reduce the risk of fire and burns, do not install this lighting system where the exposed bare conductors can be shorted or contact any conductive materials.
- Make sure all connections are tight.
- Do not install any luminaire closer than 6 inches from any curtain, or similar combustible materials.
- Turn off electrical power before modifying the lighting system in any way.
- Install over a standard 4 inch junction box.

OVERVIEW

MP-60E canopy designed to fit all WAC Pendants. Uses a 50 watt max halogen lamp.

The pendant weight should be no more than 5 pounds. MP-60E canopy comes with a self-contained electronic transformer that may be dimmed with an electronic low voltage dimmer switch.


- 1. Unscrew "canopy nut" and remove "canopy cover" from the threaded cable grip.
- 2. Pull down the "insulation plate".
- 3. Support canopy and guide the black and white wires from the transformer into the junction box.
- 4. Connect ground wire from junction box to the green grounding wire from the base plate.
- Connect corresponding line volt wires from the junction box to transformer wires (white wire connect to white wire and black wire connect to black wire), with wire nuts (supplied). Tuck excess wire into the junction box.
- 6. Attach the "base plate" to the junction box using the slotted holes and screws.
- 7. Re-attach "insulation plate".




Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585 MP-60E

PENDANT INSTALLATION


1. Make the desired cut of the "braided cord" for proper mounting height. Trim 1/8" of insulation from the inner wire.



2. Feed the "braided cord" through "canopy nut" and "canopy cover". Push up the "cable grip" top and feed the braided cord until 3" braided cord comes out from side hole.



- 3. Position the "side collar" (supplied) so that a small section (1/16") of "braided cord" protrudes from the top of the collar.
- 4. Feed the "braided cord" and "side collar" into the end of the "wire ring" and tighten the set screw with allen wrench (supplied).
- 5. Use wire nuts (supplied) to connect the protruding braid cord to the wire coming from the transformer.
- 6. Raise the "canopy cover" and make sure that wires are contained in the "canopy cover".
- 7. Tighten "canopy nut".



Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585