INSTRUCTIONS: Display Fixture Model: DL-167

IMPORTANT SAFETY INSTRUCTIONS Lighted lamp is HOT:

WARNING – To reduce the risk of FIRE, ELECTRIC SHOCK, EXPOSURE TO EXCESSIVE UV RADIATION, OR INJURY TO PERSONS:

- 1. Turn off/unplug and allow to cool before replacing bulb (lamp).
- 2. Bulb (lamp) gets HOT quickly! Only contact switch/plug when turning on.
- 3. Do not touch hot lens, or guard.
- 4. Do not remain in light if skin feels warm.
- 5. Do not look directly at lighted lamp.
- 6. Keep lamp away from materials that may burn.
- 7. Use only with a 50-watt or smaller bulb (lamp).
- 8. Do not touch the bulb (lamp) at any time. Use a soft cloth. Oil from skin may damage bulb (lamp).
- 9. Do Not operate the luminaire with a missing guard.

SAVE THESE INSTRUCTIONS

Installing Lamp:

- 1. Use 12V MR16-G lamps (UV protected & glass covered), 50 watt maximum (purchase separately).
- 2. Align lamp pins with socket holes and gently press in.
- 3. Using a fine blade screwdriver, secure the lamp in the socket by tightening the two small, black slotted lampretaining screws on either side.


Installing Clamp:

- Installs on a firm flat surface, such as wood, particleboard, cubicle partition etc. Standard clamp accommodates surfaces up to 2" thick.
- 2. Use the angle adjustment knob on the side to change the angle.
- 3. Adjust the height by sliding the telescoping rods. Socket will be hot, grasp by the rods.

Accessories:

- 1. Supplied with standard clamp that opens to 2" wide.
- 2. An optional "DLC-4A-BK" clamp opens to 4".
- 3. Standard clamp may also be used on 2" diameter pipe.
- 4. Open MR16 lamps may be used in conjunction with the "LENS-CLIP" and various accessory lenses.





Retain these instructions for future service and adjustments 615 South Street, Garden City, NY 11530 Tel: (516) 515-5000 Fax (516) 515-5050 www.waclighting.com